DEPARTMENT OF TRANSPORTATION -Toll Bridge Program 333 Burma Rd.
Oakland, CA 94607
(510) 622-5660, (510) 286-0550 fax



November 11, 2010

Contract No. 04-0120F4 04-SF-80-13.2 / 13.9 Self-Anchored Suspension Bridge Letter No. 05.03.01-008498

Michael Flowers Project Executive American Bridge/Fluor, A JV 375 Burma Road Oakland, CA 94607

Dear Michael Flowers,

Submittal 697, Rev. 7 - Painting Quality Work Plan (PQWP): ZPMC

The Department has completed the review of Submittal ABF-SUB-000697R07, "Painting Quality Work Plan (PQWP): ZPMC - Surface Preparation & Painting Procedure," dated October 26, 2010. This Submittal is being "Returned for Correction," as indicated on the attached document and as outlined by the following comments:

CATEGORY A

- 1. Clarify how Appendix 1 provided in ABF-SUB00697R06 is tied to this document. There is no reference in this document to the Appendix nor to the specific requirements of applying the coating outside of the shop. Overcoat time frames for the Interzinc 22 from that submittal conflict with those listed in this document.
- 2. Section 8.5.6 Indicate the relative humidity upon which the overcoat times listed were developed. These were previously included in Revision 4 of this submittal.
- 3. Revise damaged coatings repair procedure to specify two ranges of area size and repair methods as noted.

Please note that there will be a change to the aggregate material used in the non-skid coating as provided in ABF-RFI-001937R00. Details of the aggregate will be provided in CCO No. 94.

If you have further questions, please contact Gary Lai at the Working Drawing Campus.

Sincerely,

PETER SIEGENTHALER

Resident Engineer

Attachment

file: 05.03.01, 55.0697